



*Note:- Rail cap and duplex rail must not extend beyond surface A and duplex rail surface C must be flush with surface B when assembling.*

*New Condition*

FIRST ELEVATOR JAW DUPLIX RAIL BANKING PLATE

A change from a round pin bank, in the First Elevator Jaw Duplex Rail, to a rectangular banking plate has been made, thereby eliminating wear and providing a better locating surface for the duplex rail.

APPLIED IN FACTORY TO MODELS

All new Models of 29-30-31-32-33 and Supplemental Models 5-8-9-14-25-26.

OUTSTANDING MODELS

Can be applied to outstanding models by substituting new First Elevator Jaw Duplex Rail (Assembled) as part numbers indicate.

First applied to Model 29(4)(72-90), Serial #53428.

MERGENTHALER LINOTYPE COMPANY, Brooklyn, N.Y.