



LINOTYPE IMPROVEMENT SHEET

NO. 299



OLD CONDITION



NEW CONDITION

TWO SPEED ASSEMBLER (NEW DESIGN)

A new Two Speed Assembler has been designed using pulleys instead of gears for changing speeds. An Idler Pulley located at the Assembler Driving Pulley maintains a constant pressure on Belt while shifting or during regular operation.

APPLIED IN FACTORY TO MODEL

All new Model 33, 34, 35, 36 Machines.

OUTSTANDING MODELS

Can be applied to outstanding Model 33, 34, 35, 36 Machines equipped with the Two Speed (Gear Shift) Assembler. See Mailing Sheet #579.

First applied to Model 35(4)(72-90) - Serial #61027

MERGENTHALER LINOTYPE COMPANY, Brooklyn, N.Y.

December 8, 1949

No. 299

Printed in U.S.A.