


LINOTYPE IMPROVEMENT SHEET

No. 303

First Elevator



FIRST ELEVATOR LEVER LINK SPRING

A new First Elevator Lever Link Spring (B-918) has been adopted to replace the present Spring (B-94). This results in a more uniform pressure on the lugs of matrices whether in the highest or lowest alignment position.

APPLIED IN FACTORY TO MODELS

All Model 5, 29, 30, 31, 32, 33, 34, 35, 36 Machines.

OUTSTANDING MODELS

Can be applied to all outstanding Models by substituting B-918 for B-94.

First applied to Model 5, Serial #63691

MERGENTHALER LINOTYPE COMPANY, Brooklyn, N.Y.

September 14, 1950.

No. 303

Printed in U.S.A.